

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 07


Township: 7 North

Range: 1 East

Corner ID: Polk A-05

Monument Description & Remarks: 1" pinched Iron Pipe 2" below ground. Survey Sign 4.5ft above ground at point B

References On File: Ben E. Bledsoe survey, The Shores (1989), on file in Recorder Office Plat Book 8 page 260 and Eric L. Deckard survey, Terre Haute Realty (2005), on file in Recorder Office (IN2005024522)




I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code and the above data is given under my hand and seal this 24th day of May, 2012.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

08-21-2012



MONUMENT RECORD


Corner I.D. #

POLK A - 5

STATE OF INDIANA - COUNTY OF MONROE

Section 7, Township 7 NORTH, Range 1 EAST

Monument Description & Remarks: 1" GALVANIZED IRON PIPE MARKS THE
NORTH WEST CORNER OF SEC. 7



State of Indiana

County of MONROE

I, STEVEN V. FARKAS *St V Farkas*, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 14th day of MARCH, 2001 A.D.

Space
Reserved For
Recording
Officer


Indiana Registered Land Surveyor No. _____ or

United States Government Agency

MONROE COUNTY SURVEYOR
Title

Field Book:

Page:



Sketch
O Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Perpetuation Record

Monument and accessories established. Include brief description of area.

Ser. corner for Sec 6-7 is 250 IKS south of
Sec. " common + 7N 1W

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc.

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Index No. E-1
(Alphabetical - Numerical)

LAND CORNER RECORD (RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E 2nd Mer. N.F. Hoosier County Monroe State IND.
Section Corner common to sections 6 and 7

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1814</u>		Year of search _____	By _____
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found _____	
Bearing Trees Species <u>Hickory</u> <u>Beech</u> Diameter <u>6"</u> <u>10"</u> Bearing <u>N60W</u> <u>S40W</u> Distance <u>13 IKS</u> <u>32 IKS</u>		Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____	
Subsequent Corner Restoration Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ (Original, concrete post, iron rod, etc.)		Evidence of Subsequent Corner Restoration Found Year of search _____ By _____ _____ _____ _____	
Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____		Bearing Trees, Reference Objects _____ _____ _____ _____	